


Flat Bars



DIE #	A	B	C	WT/FT
SS2483	0.500	0.188	Full R.	0.103
SS0385	0.500	0.500	0.015	0.300
SS2426	0.625	0.125	0.015	0.094
SS0474	0.625	0.250	0.015	0.187
SS2201	0.750	0.125	0.015	0.113
SS2025	0.750	0.188	Full R.	0.160
SS1608	0.750	0.190	0.030	0.170
SS0280	0.750	0.250	0.030	0.224
SS2988	0.750	0.375	0.125	0.322
SS3865	0.750	0.500	0.015	0.450
SS0386	0.750	0.750	0.015	0.676
SS3966	0.813	0.813	0.060	0.788
SS4128	0.875	0.750	0.030	0.787
SS1589	1.000	0.100	0.015	0.120
SS1988	1.000	0.125	0.015	0.150
SS0049	1.000	0.188	0.032	0.224
SS1917	1.000	0.250	0.010	0.300
SS0962	1.000	0.250	0.125	0.284
SS3440	1.000	0.250	0.125	0.284
SS0269	1.000	0.313	0.015	0.376
SS1609	1.000	0.375	0.030	0.450
SS2739	1.000	0.375	0.094	0.440
SS1970	1.000	0.500	0.015	0.600
SS3602	1.000	0.625	0.015	0.750
SS2196	1.000	0.750	0.015	0.900
SS0395	1.000	1.000	0.015	1.200
SS1575	1.112	0.250	0.031	0.332
SS0499	1.250	0.250	0.015	0.376
SS1611	1.250	0.500	Full R.	0.685
SS3783	1.250	0.625	0.015	0.937
SS3843	1.250	0.750	0.015	1.124
SS3842	1.250	1.000	0.015	1.500
SS1606	1.250	1.250	0.125	1.859
SS2205	1.500	0.125	0.015	0.224
SS0382	1.500	0.188	0.015	0.338
SS0960	1.500	0.250	0.030	0.449
SS2192	1.500	0.375	0.015	0.674
SS0738	1.500	0.500	0.015	0.900
SS0396	1.500	0.500	0.125	0.884
SS1045	1.500	1.500	0.015	2.700
SS1651	1.740	0.340	Full R.	0.680
SS2472	1.750	0.250	0.015	0.524
SS3439	1.750	0.285	0.030	0.598
SS2127	1.750	0.300	0.125	0.614
SS3684	1.750	0.375	0.015	0.787
SS0792	1.750	1.250	0.125	2.609
SS1141	2.000	0.125	0.015	0.300
SS0179	2.000	0.188	0.015	0.451
SS1736	2.000	0.188	Full R.	0.442
SS1409	2.000	0.250	0.015	0.550
SS0080	2.000	0.250	0.030	0.599
SS1717	2.000	0.250	Full R.	0.584
SS3208	2.000	0.313	0.030	0.749
SS0619	2.000	0.375	0.010	0.900
SS2803	2.000	0.375	0.094	0.892
SS2978	2.000	0.375	0.188	0.864
SS1983	2.000	0.500	0.015	1.200
SS0087	2.000	0.625	0.015	1.500
SS1699	2.000	0.750	0.015	1.800
SS2083	2.000	1.000	0.015	2.400
SS0143	2.000	1.250	0.125	2.984
SS2554	2.250	0.375	0.015	1.013
SS2887	2.370	0.375	0.015	1.067
SS3449	2.375	0.250	0.015	0.713

DIE #	A	B	C	WT/FT
SS0290	2.500	0.125	0.015	0.376
SS0383	2.500	0.188	0.015	0.564
SS1918	2.500	0.250	0.010	0.750
SS3438	2.500	0.250	0.125	0.734
SS1487	2.500	0.500	0.015	1.250
SS1701	2.500	0.625	0.015	1.874
SS2076	2.500	0.750	0.010	2.250
SS1751	2.984	0.188	0.010	0.673
SS0694	3.000	0.125	0.015	0.450
SS0180	3.000	0.188	0.015	0.677
SS1214	3.000	0.188	Full R.	0.667
SS0613	3.000	0.250	0.015	0.900
SS2509	3.000	0.313	Full R.	1.100
SS1959	3.000	0.375	0.010	1.350
SS1957	3.000	0.500	0.010	1.800
SS2203	3.000	0.750	0.015	2.700
SS1922	3.000	1.000	0.010	3.600
SS0423	3.500	0.188	0.015	0.790
SS0943	3.500	0.250	0.015	1.050
SS1174	3.500	0.281	0.015	1.050
SS3459	3.500	0.880	0.015	3.696
SS3111	4.000	0.125	0.015	0.600
SS0384	4.000	0.188	0.015	0.902
SS1112	4.000	0.250	0.015	1.200
SS0587	4.000	0.250	0.062	1.198
SS1603	4.000	0.375	0.020	1.800
SS1737	4.000	0.375	0.063	1.796
SS1690	4.000	0.500	0.010	2.400
SS3633	4.000	0.625	0.015	3.000
SS1921	4.000	0.750	0.010	3.600
SS1923	4.000	1.000	0.010	4.800
SS2834	4.500	0.250	0.015	1.350
SS1072	4.500	0.437	0.015	2.359
SS2926	4.500	0.500	0.010	2.700
SS1619	4.500	0.594	0.015	3.208
SS3703	4.750	0.125	0.015	0.713
SS0348	5.000	0.250	0.015	1.500
SS1958	5.000	0.375	0.010	2.250
SS1773	5.000	0.500	0.015	3.000
SS0450	5.750	0.188	0.015	1.297
SS2465	5.750	0.250	0.015	1.724
SS0076	6.000	0.125	0.015	0.900
SS0154	6.000	0.250	0.015	1.800
SS1919	6.000	0.375	0.010	2.700
SS1920	6.000	0.500	0.010	3.600
SS2209	6.000	0.750	0.015	5.400
SS2373	6.000	1.000	0.015	7.200
SS3352	7.000	0.250	0.015	2.100
SS4071	8.000	0.125	0.015	1.200
SS2769	8.000	0.188	0.015	1.805
SS2082	8.000	0.250	0.015	2.400
SS1437	8.000	0.375	0.015	3.600
SS2661	8.000	0.500	0.015	4.800
SS3910	8.500	0.250	0.015	2.550
SS2813	9.000	0.125	0.015	1.350
SS1343	9.000	0.250	0.015	2.700
SS1512	9.000	0.375	0.015	4.050
SS1746	10.000	0.140	0.010	1.680
SS3525	10.000	0.375	0.015	4.500
SS1520	12.000	0.250	0.015	3.600