



'T' Bars



DIE #	A	B	C	D	E	F	WT/FT
SS3463	0.750	1.500	0.125	0.125	0.015	0.015	0.318
SS3036	1.000	1.000	0.125	0.125	0.030	0.030	0.281
SS3196	1.000	2.000	0.100	0.100	0.015	0.015	0.348
SS1345	1.125	1.500	0.125	0.125	0.080	0.010	0.378
SS1744	1.125	3.000	0.125	0.125	0.030	0.030	0.599
SS1134	1.188	4.000	0.187	0.125	0.030	0.030	1.049
SS0094	1.188	4.500	0.188	0.188	0.125	0.015	1.248
SS3844	1.500	1.500	0.125	0.125	0.015	0.015	0.431
SS3624	1.500	3.000	0.188	0.188	0.015	0.015	0.970
SS1772	2.000	2.000	0.125	0.125	0.015	0.015	0.581
SS3280	2.000	2.000	0.250	0.250	0.015	0.015	1.124
SS0127	3.000	3.000	0.180	0.180	0.015	0.015	1.258
SS3307	3.000	4.000	0.180	0.180	0.015	0.015	1.472

'Z' Bars



DIE #	A	B	C	D	E	F	WT/FT
SS3062	0.500	0.500	0.500	0.090	0.010	0.010	0.143
SS1578	1.230	1.000	1.000	0.080	0.063	Full R.	0.295
SS0129	3.000	1.500	0.750	0.125	0.015	0.015	0.750
SS0220	3.000	2.688	2.688	0.250	0.313	0.250	2.381

NOTE: Check actual prints to confirm all walls and corners